
	GROUP Chassis	MODEL 2009-2010MY Rio (JB)
	NUMBER CHA 030	DATE October 2010
TECHNICAL SERVICE BULLETIN		
SUBJECT: RIO (JB) REAR STRUT NOISE REPAIR		

This bulletin provides information relating to Some RIO (JB) vehicles produced from July 1, 2008 to January 27, 2010 that may experience a creaking noise emanating from the rear strut when driving on a rough road in winter weather. To remedy this condition, replace the Rear Strut Insulator and Retainer with improved parts as indicated in the required parts section.



Rio (JB) Rear Strut Assembly

File Under: <Chassis>

Circulate To:
 ☒ General Manager
 ☒ Service Manager
 ☒ Parts Manager
☒ Service Advisor(s)
 ☒ Technician(s)
 ☒ Body Shop Manager
 ☒ Fleet Repair

SUBJECT:**RIO (JB) REAR STRUT NOISE REPAIR****Service Procedure:**

For vehicles with symptom/condition mentioned above; replace the Rear Strut Insulator and Retainer with the improved version according to the applicable workshop manual procedure.

AFFECTED PRODUCTION RANGE:

Model	Production Date Range
Rio (JB)	July 1, 2008 to January 27, 2010

REQUIRED PARTS:

Part Name	Part Number		Figure
A: Retainer	55322 1G000	55322 1C000FFF	
B: Strut Insulator	55311 1G000	55311 1G000FFF	

WARRANTY CLAIM INFORMATION:

Claim Type	Causal P/N	Qty.	N Code	C Code	Repair Description	Labor Op Code	Time	Replacement P/N	Qty.
W	55322 1G000 55311 1G000	0	N29	C10	(CHA 030) Rear Retainer and Strut Insulator Replacement (One Side)	55310F00	0.4 M/H	55322 1C000FFF 55311 1G000FFF	1EA
		0			(CHA 030) Rear Retainer and Strut Insulator Replacement (Both Sides)	55310F01	0.7 M/H	55322 1C000FFF 55311 1G000FFF	1EA